

## Maximo 7.6 – Subcontractor Portal

How to use the Subcontractor Portal

How to provide an ETA.

The details on the next page will help you:

• to provide an ETA for a job

1.	Go to Estimated Start Section.					
		<b>Details</b> Attendance Assets	Log Notes D	ocuments Mitigation Events		
		Adidas (U.K.) Ltd		Custref01		
		Classification		Work Category		
		Manual Fire Door - Fault or Failure		REACTIVE		
		Priority		Service Request Created		
		1 P1 Emergency	$\land$	20-May-2022 10:30		
		Work Order Target Start		Work Order Target Finish		
		20-May-2022  13:30    Estimated Start		20-May-2022	☐ 14:30	
				Estimated Finish		
				dd-mmm-yyyy		
				Actual Einich		
		dd-mmm-vvvv	曲:	dd-mmm-vvvv	曲:	



3.	Click the clock icon to select the time.	Details Attendance Assets Log Notes Documents Mitigation Events						
		Adidas (U.K.) Ltd					Custref01	
		Classification			16	09	ork Category	
		Manual Fire Door - Fault o			17	10	REACTIVE	
		Priority			18	11	rvice Request Created	
		1	P1 Emergency		19	12	20-May-2022 10:30	
	w	Work Order Targ	jet Start		20	13	ork Order Target Finish	
		20-May-20	22	Ë	21	14	20-May-2022	
	Estimate	Estimated Start			22	15	timated Finish	
		07-Jun-20	22		6:09 🕒	)	dd-mmm-yyyy 📋: 🛈	
	Actua					_	Actual Finish	
		dd-mmm-yy	уу	₿ -	- :		dd-mmm-yyyy 💾	
L								

4.	Click Save Changes to save the ETA.	Appointment Entitlement	Failure Reason
		REQUIRED	Failure Class
		Permit Required	HDOORS: Doors
		Reported as Business Critical	Problem
		Reported as risk to Health and Safety	Cause
		Location	~
			Remedy
		Address	~
		UNIT 71 & 72 EAST BUILDING, , GUNWHARF QUAYS, PORTSMOUTH, PO1 3TA	
			Save Changes